

EAST Search History

EAST Search History (Prior Art)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	10/590587	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 10:37
L10	0	("200100001273").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2010/06/23 11:21
L11	1	("20010001273").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2010/06/23 11:22
L12	8	motor near2 (gear pinion) near4 (pass passing passed passes insert\$4) near2 (slot groove slit cutout cut-out)	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:25
L13	10	motor near2 (gear pinion) near2 (assembly preassembly\$4 pre-assembly\$4)	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:28
L14	124	motor near2 (gear pinion) near2 (slot groove slit cutout cut-out)	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:30
L15	71	14 and @ad<"20040226"	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:31
L16	81	(wall sidewall frame housing) near2 (slot slit groove cutout cut-out) near4 (mount\$4 insert\$4 install\$4) near2 (motor)	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:33
L17	300	motor near2 (assembly preassembly\$4 pre-assembly\$4)	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:44
L18	109221	"400"/\$.ccls. "347"/\$.ccls.	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:44
L19	0	17 and 18	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:44
L20	79912	motor near2 unit\$4	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:44

L21	1017	18 and 20 and @ad<"20040226"	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:44
L22	113325	motor near2 (wall sidewalk subwall frame support\$3)	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:45
L23	67	21 and 22	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 11:45
L24	250	(gearbox gear adj box gear adj plate gear near1 support) near4 (resin plastic polymer urethane polyurethane polycarbonate)	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 13:53
L25	153	24 and @ad<"20040226"	US-PGPUB; USPAT; USOCR	OR	ON	2010/06/23 13:53

EAST Search History (Interference)

< This search history is empty >

6/23/2010 2:01:42 PM**H:\ Workspaces\ 10590587.wsp**